

## Application instructions



5° Min application temper

METHOD. The surface to be bonded must be free from dust, grease or other contaminants.

♥ P.A. des petits carreaux - 2 avenue des Orangers 94380 Bonneuil sur Marne - FRANCE ↓ +33 (0)143 99 00 22 - ᢂ info@reflectiv.com - ᠲ www.reflectiv.com

Vou will need the following tools :











1 Spray bottle filled with water and ...

... a few drops of washing solution

1 Razor blade window scraper

1 Rubber saueeaee 1 Cutter 1 Roll of paper towels



Using the window scraper and the

spray bottle of soapy water , clean

the window pane thoroughly.

With the help of 2 pieces of scotch

tape separate the film from its

protective liner.

Spray the film to allow the squeegee

to slide easily over it.



Wipe the window frame with

a rubber squeegee and

a paper to

Using the cutter, cut a piece of film to a size 2 or 3 cm larger than the window pane

+ 2 à 3 cm



Turn the film around and apply its adhesive side to the window pane.

< 2 mm

Cut the film to within 2 mm of the window pane's edge. The film shouldn't touch the frame Then squeegee to smooth out any remaining air bubbles.

## **Our recommendations**

- Application should be done very carefully to obtain optimum results.
- If a few defects are visible after the application, they should disappear after 3 weeks.
- Do not clean the film during the drying period (3 to 5 weeks).
- After the drying period, the film may be cleaned with slightly soapy water. Do not use abrasives or products containing alcohol. Please refer to our prescription table or contact us for any question



To attain a good adherence, working from top to bottom, scrape with the squeegee from the center towards the right and left edges.



KITPOS Surface < 3m<sup>2</sup>

MATPOS

Surface

> 3m<sup>2</sup>